



11. WIRING DIAGRAM



COMBINATION SWITCH CONTINUITY

	IG	E	BAT	L ₀	ST
OFF	○	○			
ON			○	○	
ST					○

- BI BLACK
- Y YELLOW
- Bu BLUE
- G GREEN
- R RED
- W WHITE
- Br BROWN
- O ORANGE
- Lb LIGHT BLUE
- Lg LIGHT GREEN
- P PINK
- Gr GRAY



COMBINATION SWITCH CONTINUITY

	IG	E	BAT	L ₀	ST
OFF	○	○			
ON			○	○	
ST					○

- BI BLACK
- Y YELLOW
- Bu BLUE
- G GREEN
- R RED
- W WHITE
- Br BROWN
- O ORANGE
- Lb LIGHT BLUE
- Lg LIGHT GREEN
- P PINK
- Gr GRAY