


7. WIRING DIAGRAM

CB360 (U.S.A. TYPE)



C8360 (USA. TYPE)

FUSE

FUSE

FUSE 15A

WIRING DIAGRAM

SPEEDOMEYER

CONTACT BREMER

SQUON RECHNER

VII. SERVICE DATA